ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
13

Ward Name
Mallasandra

Street ID
W0103, W0144, W0105, I0117, W0101, W0205, W0170, W

Street Name
NA, 3rd Crs, Om Shakthi Lyt 1st Crs, Vinayaka Lyt 2nd Crs, Vinayaka Lyt 1st Crs, Kaveri Nagar Near S

Significant Landmark
Ravindra Nagra Surrounding Area

Segment No.
13/C-W0103/S094514

Total Length (m)
1735.06

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	170.01	77.514809	13.051286	77.515302	13.052744	Pipeline Road	Dead End
2	69.96	77.514522	13.051500	77.514752	13.052091	Pipeline Road	Dead End
3	56.71	77.514253	13.051720	77.514420	13.052206	Pipeline Road	Dead End
4	584.75	77.518650	13.048438	77.520077	13.053507	Pipeline Road	10th Cross Ravindra Nagara
5	52.04	77.519127	13.051364	77.519567	13.051176	1st Main Ravindra Nagara	2nd Main Ravindra Nagara
6	197.28	77.519114	13.051401	77.519650	13.053104	4th Cross Ravindra Nagara	10th Cross Ravindra nagra
7	126.18	77.516351	13.053209	77.517488	13.052969	4th Main Ravindra Nagara	Shooting Bunglow Road
8	162.65	77.516686	13.052253	77.516976	13.053695	9th Corss Ravindra Nagra	Dead End
9	52.12	77.516482	13.053802	77.516955	13.053719	5th Cross	Shooting Bunglow Road
10	154.37	77.515153	13.054863	77.516560	13.054654	Shooting Bunglow Road	BHEL MIni Colony Road
11	108.99	77.514790	13.053941	77.515108	13.054875	Pipe line Road	5th cross Vijayalakshmi L/o

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements To Roads And Drains At Ravindra Nagra Surrounding Area In Ward No 13 Shettyhalli Sub Division

Sanctioned Estimated Amount (Rs.)
8400000

Sanctioned Year
2019

Year
2019 - 2020

Type of Work
Others

Other Work Type

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0103, W0144, W0105, I0117,

Scanned by CamScanner

Tender	Work Details	Job No. / Work Code
NO e Tender		[illegible]
Work Order No.	Work Order Date	Period of Extention
BBMP/EE/DD/WO/[illegible]/2019-20	14/02/2020	
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
09/12/2020	13/12/2021	Yes

Contractor Details		
Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked / Released (Rs)
GRDL		0.00
Phone No.	E-Mail ID	
[illegible]		

Ward No: 13 Ward Name: [illegible] Street ID: [illegible]

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Venkateshappa
Date of Inspection	**Remarks**	
27/04/2021		

Category	Image	Photo Remark
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0103, W0144, W0105, I0117,

Scanned by CamScanner

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	08/07/2021	17/06/2021	APPROVED
EE	EE DAS	31/05/2021	27/05/2021	COMPLETED
AEE	M Nagesh Murthy	27/04/2021	27/05/2021	Completed
AE	Venkateshappa	27/04/2021	27/05/2021	Forwarded
AE	Venkateshappa	27/04/2021	27/05/2021	Created

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0103, W0144, W0105, I0117,

Scanned by CamScanner